

[REDACTED]

Below is an analysis of the event 2/2/2021 on the coker at 7:35 am. [REDACTED]

- [REDACTED]
[REDACTED]
- [REDACTED]
- [REDACTED]
[REDACTED]

[REDACTED]
[REDACTED]

Description of event

Drum 3 vent sprayed material on the unit this morning at 7:35 hrs. By observation, the material on the ground was a mixture of coke fines, coke particles <1 in, pitch and water. [REDACTED]

[REDACTED]

[REDACTED]





Similar Events

1. Last week a similar event occurred with oily/water mixture covering the wet gas compressor area [REDACTED]

[REDACTED]

[REDACTED]